

**INDEPENDENT TESTING LAB**

830 ROBINWOOD COURT, TRAVERSE CITY, MI 49686

PH: 231-929-0905

FAX: 231-929-0894

www.gtanalytical.com

Company: RIVERSIDE
Name:
ClientProj: 190011-7800
GTA ProjNo: 110220-1

Site Addr: ELMIRA 23 VALVE BOX

Sampled By: LMH-J/ECT
Date Rec: 11/2/2020
Time Rec: 1:46 PM

Sample No.	Sample ID	Date Sampled	Time Sampled	Sample Matrix
1	NORTH SW	11/2/2020		SOIL
2	SOUTH SW	11/2/2020		SOIL
3	EAST SW	11/2/2020		SOIL
4	WEST SW	11/2/2020		SOIL
5	F-1	11/2/2020		SOIL
6	F-2	11/2/2020		SOIL
7	F-2 + 4'	11/2/2020		SOIL

ELECTRONIC SIGNATURE REPORT. This is a final report for the following pages of data for the samples specified above. All analysis was performed by the methods stated and all quality control measures required were completed. All quality control information is available upon request.

Kirk Chase

Kirk L. Chase/Chemist
Grand Traverse Analytical
830 Robinwood Court
Traverse City, MI 49686
Ph: 231-929-0905
Fx: 231-929-0894
SP: 231-590-0291
kirk@gtanalytical.com

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 1

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: NORTH SW CHLORIDE EPA 300.0	ND	87	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 2

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: SOUTH SW CHLORIDE EPA 300.0	ND	87	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 3

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: EAST SW CHLORIDE EPA 300.0	ND	89	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 4

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: WEST SW CHLORIDE EPA 300.0	ND	82	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 5

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: F-1						
	CHLORIDE EPA 300.0	ND	88	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 6

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
SAMPLE ID: F-2							
CHLORIDE EPA 300.0		350	97	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: RIVERSIDE
PROJECT NO: 190011-7800
LOCATION: ELMIRA 23 VALVE BOX

GTA PROJECT NO: 110220-1
GTA SAMPLE NO: 7

DATE SAMPLED: 11/2/2020
TIME SAMPLED:
DATE RECEIVED: 11/2/2020
TIME RECEIVED: 1:46 PM

MI
SAMPLED BY: LMH-J/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: F-2 + 4'						
	CHLORIDE EPA 300.0	320	91	mg/Kg (PPM)	LV	11/2/2020	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

**INDEPENDENT TESTING LAB**

830 ROBINWOOD COURT, TRAVERSE CITY, MI 49686

PH: 231-929-0905

FAX: 231-929-0894

www.gtanalytical.com

COMPANY: RIVERSIDE

NAME:

PROJECT NO: 190011-7800

LOCATION: ELMIRA 23 VALVE BOX

MI

GTA PROJECT NO: 110220-

SAMPLED BY: LMH-J/ECT

DATE SAMPLED: 11/2/2020

TIME SAMPLED:

SAMPLE MATRIX: SOIL

DATE RECEIVED: 11/2/2020

TIME RECEIVED: 1:46 PM


MOISTURE

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>
	SAMPLE ID: NORTH SW					
	% MOISTURE EPA 3550C	7.0	0.050	% OF SAMPLED	AS	11/2/2020
	SAMPLE ID: SOUTH SW					
	% MOISTURE EPA 3550C	8.4	0.050	% OF SAMPLED	AS	11/2/2020
	SAMPLE ID: EAST SW					
	% MOISTURE EPA 3550C	4.6	0.050	% OF SAMPLED	AS	11/2/2020
	SAMPLE ID: WEST SW					
	% MOISTURE EPA 3550C	6.6	0.050	% OF SAMPLED	AS	11/2/2020
	SAMPLE ID: F-1					
	% MOISTURE EPA 3550C	8.5	0.050	% OF SAMPLED	AS	11/2/2020
	SAMPLE ID: F-2					
	% MOISTURE EPA 3550C	7.3	0.050	% OF SAMPLED	AS	11/2/2020
	SAMPLE ID: F-2 + 4'					
	% MOISTURE EPA 3550C	7.3	0.050	% OF SAMPLED	AS	11/2/2020

CHAIN OF CUSTODY

PROJECT NUMBER 190011-7800	SITE NAME/ADDRESS Elmira 23 Valve Box	COMPANY/NAME RIVERSIDE
SAMPLED BY LMH-J	COMPANY ECT	GTA PROJECT # 110220-1


SAMPLE INFORMATION

#	SAMPLE ID	DATE SAMPLED	TIME	MATRIX	ANALYSIS
1	NORTH SW	11-2-20		Soil	CL
2	SOUTH SW				
3	EAST SW				
4	WEST SW				
5	F-1				
6	F-2				
7	F-2+4'				
					

BILL TO:

ECT

REPORT TO:





RELEASED BY

DATE/TIME

RECEIVED BY

DATE/TIME

 11-2-20

 11/2/20 1:46p

REQUESTED TAT

☐ STANDARD

☒ 1 BUSINESS DAY

☐ 2 BUSINESS DAYS

☐ 3 BUSINESS DAYS