

**INDEPENDENT TESTING LAB**

830 ROBINWOOD COURT, TRAVERSE CITY, MI 49686

PH: 231-929-0905

FAX: 231-929-0894

www.gtanalytical.com

Company: VCP
Name:
ClientProj: 200837-2400
GTA ProjNo: 040921-3

Site Addr: EL MAC HILLS A1-i8

Sampled By: JSL/ECT

Date Rec: 4/9/2021

Time Rec: 3:45 PM

Sample No.	Sample ID	Date Sampled	Time Sampled	Sample Matrix
1	F-3	4/9/2021	10:30 AM	SOIL
2	F-5	4/9/2021	11:28 AM	SOIL
3	F-6	4/9/2021	11:48 AM	SOIL
4	SS-1	4/9/2021	9:45 AM	SOIL
5	SS-5	4/9/2021	10:11 AM	SOIL
6	SS-6	4/9/2021	11:11 AM	SOIL
7	SS-7	4/9/2021	11:32 AM	SOIL

ELECTRONIC SIGNATURE REPORT. This is a final report for the following pages of data for the samples specified above. All analysis was performed by the methods stated and all quality control measures required were completed. All quality control information is available upon request.

Kirk Chase

Kirk L. Chase/Chemist
Grand Traverse Analytical
830 Robinwood Court
Traverse City, MI 49686
Ph: 231-929-0905
Fx: 231-929-0894
SP: 231-590-0291
kirk@gtanalytical.com

**INDEPENDENT TESTING LAB**

830 ROBINWOOD COURT, TRAVERSE CITY, MI 49686

PH: 231-929-0905

FAX: 231-929-0894

www.gtanalytical.com

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 1

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 10:30 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: F-3						
	CHLORIDE EPA 300.0	120	95	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 2

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 11:28 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: F-5						
	CHLORIDE EPA 300.0	280	92	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 3

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 11:48 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: F-6						
	CHLORIDE EPA 300.0	360	99	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 4

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 9:45 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
SAMPLE ID: SS-1							
CHLORIDE EPA 300.0		ND	90	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 5

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 10:11 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: SS-5						
	CHLORIDE EPA 300.0	ND	100	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 6

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 11:11 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: SS-6						
	CHLORIDE EPA 300.0	ND	99	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C

COMPANY: VCP
PROJECT NO: 200837-2400
LOCATION: EL MAC HILLS A1-18

GTA PROJECT NO: 040921-3
GTA SAMPLE NO: 7

DATE SAMPLED: 4/9/2021
TIME SAMPLED: 11:32 AM
DATE RECEIVED: 4/9/2021
TIME RECEIVED: 3:45 PM

MI
SAMPLED BY: JSL/ECT

SAMPLE ANALYSIS

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>	<u>Sample</u>
	SAMPLE ID: SS-7						
	CHLORIDE EPA 300.0	170	91	mg/Kg (PPM)	TR/AS	4/10/2021	SOIL

ND = NOT DETECTED, RESULT < LOD
LOD = LIMIT OF DETECTION
s.u. = STANDARD pH UNITS REPORTED AT 25 C



INDEPENDENT TESTING LAB

830 ROBINWOOD COURT, TRAVERSE CITY, MI 49686

PH: 231-929-0905

FAX: 231-929-0894

www.gtanalytical.com

COMPANY: VCP

NAME:

PROJECT NO: 200837-2400

LOCATION: EL MAC HILLS A1-18

MI

GTA PROJECT NO: 040921-

SAMPLED BY: JSL/ECT

DATE SAMPLED: 4/9/2021

TIME SAMPLED: 10:30 AM

SAMPLE MATRIX: SOIL

DATE RECEIVED: 4/9/2021

TIME RECEIVED: 3:45 PM

MOISTURE

<u>No:</u>	<u>Analysis</u>	<u>Concentration</u>	<u>LOD</u>	<u>Units</u>	<u>Analyst</u>	<u>Date Completed</u>
SAMPLE ID: F-3	% MOISTURE EPA 3550C	8.4	0.050	% OF SAMPLE	AS	4/9/2021
SAMPLE ID: F-5	% MOISTURE EPA 3550C	8.7	0.050	% OF SAMPLE	AS	4/9/2021
SAMPLE ID: F-6	% MOISTURE EPA 3550C	8.1	0.050	% OF SAMPLE	AS	4/9/2021
SAMPLE ID: SS-1	% MOISTURE EPA 3550C	5.4	0.050	% OF SAMPLE	AS	4/9/2021
SAMPLE ID: SS-5	% MOISTURE EPA 3550C	8.1	0.050	% OF SAMPLE	AS	4/9/2021
SAMPLE ID: SS-6	% MOISTURE EPA 3550C	5.7	0.050	% OF SAMPLE	AS	4/9/2021
SAMPLE ID: SS-7	% MOISTURE EPA 3550C	7.2	0.050	% OF SAMPLE	AS	4/9/2021

CHAIN OF CUSTODY

PROJECT NUMBER 200837-2400	SITE NAME/ADDRESS El Mac Hills A1-18	COMPANY/NAME VCP
SAMPLED BY JSL	COMPANY ECT	GTA PROJECT # 040921-3

SAMPLE INFORMATION

#	SAMPLE ID	DATE SAMPLED	TIME	MATRIX	ANALYSIS
1	F-3	4/9/2021	10:30	Soil	Chloride
2	F-5		11:28		
3	F-6		11:48		
4	SS-1		9:45		
5	SS-5		10:11		
6	SS-6		11:11		
7	SS-7		11:32		

BILL TO:

VCP

REPORT TO:

Jeremy Lewandowski

RELEASED BY

DATE/TIME

RECEIVED BY

DATE/TIME

[Signature]

4/9/21 3:45pm

[Signature]

4/9/21 3:45p

REQUESTED TAT



STANDARD

☐ **1 BUSINESS DAY**

☐ **2 BUSINESS DAYS**

☒ **3 BUSINESS DAYS**